INSTRUCTIONS

- subsequent record used to evaluate the corner position. 1. Original a.
- Description of evidence found, note discrepancies in the record.
 Description of monument and accessories set to perpetuate the corner position
- 4. Sketch of corner, show all pertinent data.
- 5. Certification must be signed and sealed by Land Surveyor licensed in the State of Montana
- 6. Fill in index information and show the corner's approximate location within the section diagram.

CERTIFIED CORNER RECORDATION

Corner S1/4 SEC. 21 T. 35N R. 55E P.M.M. SHERIDAN County 1. Had copy of the Original GLO Plat and GLO notes. Had a copy of the quad map. 2. Found #4 Rebar. 3. Accepted Rebar Corner. 4. See Sketch as Shown. FOUND 2"AC 15258LS STATE HWY 16 ANTELOPE -STATE HWY 16 -PLENTYWOOD. (2) 48" CMP 67 5284. HAY MEADOW HAY MEADOW FOUND #4 REBAR ON INSIDE TOE OF EAST BANK FOUND #5 REBAR 2642.58 E CREEK SET FENCEPOST 0.3' WEST OF FOUND REBAR CERTIFICATION SLETVOLD ound Party Chief TROY **JENSEN** Surveyor & Seal 1-10-06 Reg. No. 15258LS Employers INTERSTATE ENGINEERING INC SKETCH OF CORNER IE#S05-9-299 464930 BOOK: 613 PAGE: 1648 Pages: 1 Offic STATE OF MONTANA SHERIDAN COUNTY _ . This "corner recol RECORDED: 06/01/2006 2:25 KOI: CORNER REC 21 Sec. JUNE A. JOHNSON CLERK AND RECORDER BY: Morma Jaulson WQS | FEE: \$0.00 TO: INTERSTATE ENGINEERING, INC. PO BOX 648, SIDNEY, MT 59270 book No. County Official Cross Index No. R-11 T. 35N R. 55E PMM Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

• corner this sheet