## PLSS Corner Collection System Data Sheet

Meridian: <u>PMM</u> Tier: <u>5N</u> Range: <u>5E</u> Section(s): <u>31</u> County: <u>Gallatin</u>

## GCDB Point ID: MT200050N0050E0 100100

 Employee Name:
 Ryan Dee
 Date:
 10/21/2010
 Time:
 1:00

Found: Original sandstone, 17x14x6, lying flat. Monument appears in original position and fell west. Therefore I reset in place with 'CC' on east face with 6 grooves, 'SC' on north face with 6 notches and 6 notches in south edge. Found scattered mound of stone along east side of monument (as called for in notes). Monument is situated at intersection of a dilapidated fence extending north and a dilapidated fence extending east. I re-raised a mound of stone east of corner.



Latitude: 46°08'31.9757"N

Longitude: 111°09'34.2689"W

Datum NAD83(2007)

Approximate orthometric elevation: <u>5053 ft.</u>

This corner was located as part of a PLSS enhancement project. The location of this corner was not used as control for any legal surveys during this exercise. Horizontal accuracy 1 meter or less.