Mature Cottonwoods no understory vegetation. Bank undercut and eroded during last flood event.

Segment 12