INSTRUCTIONS

and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

1595 K CERTIFIED CORNER RECORDATION WEST QUARTER Corner <u>SECTION</u> 29 58E P.M.M.__ _R. _ T. 2N CARTER _County FOUND GOVERNMENT BRASS CAP MONUMENT. REFERENCED ACCORDING TO THE SKETCH BELOW: BRASS CAP REBAR W/CAP BRASS 236.6' CAP 377. 30 29 BRASS 31 32 REBAR CERTIFICATION Charles M. Madler certify the information shown herein is true and Signature Ground Par Charles M. Madler Cherry Charles M. Madler Cherry Charles M. Madler Cherry Charles M. Madler Cherry Employer: Professional Land Services SKETCH OF CORNER 29 Office of Clerk and Recorder, County of ____. This "corner Sept 5, 1986 record" was filed for record on __ was noted on the cross-index plat and is assigned page No. JANE M. BREWSTE

JANE M. BREWSTE

ARTER COUNTY CLERK AND R

County Official

County Official

Cross Index No. T-5 T. 2N R. 58E PMM • - corner this sheet

159506