nd/or subsequent record used to evaluate the corner position. 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or our sted conners. 3. Description of monument and accessories set to perpetunte the corner position. 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography files, position of accessories, etc. 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana. 6. Fill in Cross Index 4. Section Diagram at boltom of sheet.	*	
CERTIFIED CORNER RECORDATION		

<u>County</u>

INSTRUCTIONS

5N R. 9W P.M.M. Deer Lodge

32 33

SEC

Corner

'Set a charred stake in mound of earth with pits' 1869 GLO Record:

March, 1977 Corner Form (1888S): 'Found a 2"x2" hub set in plowed field by the Montana Highway Department as the corner to Sections 28,29,32, & 33, T6N, R9W, MPM. The station and distance are shown on the Highway plans to a set stone in place found by the original Highway Survey in 1966.' Two 5/8" rebars were set in E-W fence as references to the hub, 39.58 feet Northwest and 47.10 feet Northeast. A tie to the NW corner of Section 32 is shown, N.89°03'02"W., 5252.97 feet.

Corner position falls in cultivated field, where we find remains March, 1993, Found: of old stake and hub, buried 0.3 feet below ground surface. The Northeast RM is found and fits the position of the found hub. We find no evidence of the 1977 reference in the NW. A tie by made this survey to the NW corner of Section 32, (re-established this survey) shows N.89°15'58"W., 5253.43, also confirming the position of the found hub.

March, 1993, Set: At the position of the found hub, set 2-1/2"x30" alum. pipe with 3-1/4" PCI alum. cap, 1 foot below surface of cultivated field, cap marked as shown below.

To reference the corner we place a 1-1/2" alum cap (2923S) on the found NE rebar, and set a 5/8" rebar with 1-1/2" alum. cap (2923S). Both R.M.'s are under E-W fence line and caps are stamped RM 1 and RM 2.

- R.M. No. 1 (found) brs. N.50°E., 47.10 feet.
- R.M. No. 2 (set) brs. N.63°W., 48.54 feet.
- Galvanized post set at each R.M.

ANST	CERTIFICATION			
CUINDULT	<u>, Duane G. Schmitz</u>			
	certily the information shown herein is true and correct.			
	1 un i I Schmill			
EXUN RSW	Signature Ground Party Chiel 24			
	, Richard A. Ainsworth			
N 529 528 Z	and the the table Corport Honord correctly represents work performed			
532 533	by me or under my direction in compliance with the "Corner Recordation Act" (20-22-101, et seq. M.C.A.)			
	he and with			
29235	Signature of Surveyor & Seal			
1993 189	Date: 12/93 Reg. No. 29235			
401 778	Date: 17.75 neg. No. 25205			
	Employer: Professional Consultants, Inc			
SKETCH OF CORNER	Sec. 28			
Deer Lodge	This "corner			
Office of Clerk and Recorder, County of <u>Deer Lodge</u> . This "corner				
record" was filed for record on <u>Alecenture</u> 16,1974				
in the last and is assigned page No. 376 in the interview of the				
was noted on the cross-index plat and is assigned page No/6, in				
Millie (Inder	son-Deputy			
book No County Official				
· ·	•			
	т. <u>БN в. 9W рим</u> • - corner this sheet			
Adouted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors				