67640

1. ORIGINAL AND/OR SEQUENT RECORD USED TO EVALUATE THE CORNER F
2. DESCRIPTION OF L ...NCE FOUND, NOTE DISCREPANCIES IN THE RECORD, S METHOD OF ESTABLISHING LOST OR OBLITERATED CORNERS.
3. DESCRIPTION OF MONUMENT AND ACCESSORIES SET TO PERPETUATE THE CORNER POSITION.
4. SKETCH OF CORNER, SHOW ALL PERTINENT DATA WHICH CAN BEST BE SHOWN IN A SKETCH EXAMPLE, CORNER MARKINGS, TOPOGRAPHY TIES, POSITION OF ACCESSORIES, ETC.
5. CERTIFICATION MUST BE SIGNED AND SEALED BY LAND SURVEYOR REGISTERED IN THE STATE OF MONTANA.
6. FILL IN CROSS INDEX AND SECTION DIAGRAM AT BOTTOM OF SHEET.

## CERTIFIED CORNER RECORDATION

DOOK

1 PAGE 598

CORNER East Quarter SEC. 10, T. 7 N., R. 59 E., P.M.M., Fallon COUNTY, MT

ORIGINAL RECORD : Surveyed by Robert F. Scott & Harry E. Fearnall in 1908.

> Set a sandstone 16x12x10 ins., 11 ins. in the ground for 1/4 Sec. Cor. marked 1/4 on W. face; dig pits, 18x18x12 ins. N and S. of stone 3 ft. dist.; and raise a mound of earth, 3%

ft. base, 1% ft. high, W. of cor.

EVIDENCE FOUND:

No evidence of original corner, position of corner falls in

roadway.

SET:

book No.\_

Fee: N/C


BOOK

Re-established 1/4 corner by single proportionate measurement

from the found section corner to the south and the re-established section corner to the north. At the corner point set a 5/8"x18" rebar with a 2" alum. cap 6" below gravel

roadway. Cap stamped as shown

1/4 S 10 ! S 11 1995 7155LS



Cross Index No. G-17 T. TN R.59E PMM

corner this sheet

County Official

was noted on the cross—index plat and is assigned page No

1 PAGE 598