BOOK

1 PAGE 374

INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Northwest Section Corner __of Section 34 T. 7 N

Fallon

County

Found 1" pipe set in the corner of barbed-wire fence. Pipe fit surrounding control and accepted as the NW Section Corner. Set a $2\frac{1}{2}$ "x24" Iron Pipe with an aluminum cap marked according to the sketch below. Referenced to surrounding subdivision corners.

