CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN) 1952 government resurvey calls for brass cap at fence corner found no trace of brass cap - 2 bearing trees had been cut down am mutilated but were unmistakable

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

1973

reset corner with 2" x 24" rebar from bearing free stumps

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

W421 3 SW 21

Surveyor's Seal

I, Robert M Ryan certify that the information shown herein is true and

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form, and approve the same.

Z3585 Registration Number

DIAGRAM OF CORNER:

N.

R 26E Corner recorded on the sheet

3:20 PM "corner record" was filed for record on the day of Meember

gned page No.....

Cross Index No. R-9 8 N