

CERTIFIED CORNER RECORDATION

Corner	S 1/4	SECTION	36	Τ.	16N	R,	19E	P.M.M.	FERGUS	County
	N 1/4	SECTION	1	-	15N		19E			

ORIGINAL RECORD: Unknown.

SUBSEQUENT RECORD: (1942, E. Parker) Found original limestone firmly set. Replaced the original stone with a iron post 3 ft. long 1 in. diam. 30 ins. in the ground for the 1/4 corner., with a brass cap marked . . .raised a mound of stone 2 ft. base 1 1/2 ft. high North of corner.

(2003, Milestone) Landowner Eldon Synder reported that a GLO brass cap had been in place at the 4-way fence corner, but had been removed in a boundary dispute. At the East base of a fence corner post North x South x East x West set a 5/8" rebar with a 2" aluminum cap. Set a MARLS tag on the fence corner post.

EVIDENCE FOUND: (January, 2007) Found GLO brass cap monument 0.1' subsurface at the NE base of FCP (N-SxE-W). Found the MARLS tag on the FCP but the 5/8" rebar with 2" aluminum cap by Milestone was gone. It appears that we did not search carefully enough during the 2003 survey. The found monument was within 0.5' of the position we had previously used for this corner. My previous corner should be ignored and the BLM monument should be used.

PERPETUATION: (January, 2007) Accepted the GLO brass cap monument as found.



087009

087009