INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

3. Description of monument and accessories set to perpetuate the corner position

- Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner WEST 14 COR SECTION 7 T. 20 N. R. 19 W. P.M.M. LAKE County

- 1- SEE CERTIFIED LAND CORNER RECORDATION FORM FILED ON WORK DONE IN MAY OF 1971 BY RLS 3325 S.
- 2- FOUND A 30" GALVANIZED PIPE WITH ITS BRASS CAP TORE OFF BY HEAVY ROAD EQUIPMENT. THE TOP 10 INCHES HAVE BEEN BENT OVER AND IS ON SURFACE OF ROADWAY. BOTH RM'S ARE ALIVE AND IN GOOD CONDITION.
- 3- I REMOVED THE BENT OVER MONUMENT OF PECCED AND IN ITS PLACE I SET A 5/8" REBAR, 24" LONG, WITH A PLASTIC CAP MARKED "RLS GOIZS". THIS MONUMENT IS 6 INCHES BELOW ROAD SURFACE TO PRESERVE ITS POSITION, BEARINGS AND DISTANCES TO PMS OF RECORD CONFIRM THE LOCATION AS ESTABLISHED BY RLS 33258 DURING 1971. PINE TREE

4-RECORD R.M. TREE SET \$8" PEBAR WITH CAP AT LOCATION OF BRASS CAP MONUMENT. 6" BELOW SURFACE OF ROADWAY LANE NOT TO SCALE

CHITTICATION certify the i correct. GREGORY B. Reg. No. 9012/5 Employer: **SKETCH OF CORNER**

10.4	Sec. 7
Office of Clerk and Recorder, County of This "corner	
record" was filed for record on October 26, 1987 at 1:19 p.m. and	
microtile 308702	
was noted on the cross-index plat and is assigned No. LORIN JACOBSON CLERK & POURUER	
Vilena 1-1544	
No. County Official	1 1 1
Cross Index No. G-1 T. 20N R. 19 W PMM	corner this sheet