CERTIFIED CORNER RECORDATION

Corner	SE	Secs.	5	T.	21 N	R.	29W	Р.М., МТ	Sanders	County
I.									round for Cor. to s E edges from whi	ec.; 4,5,8&9. marked cb:
	Established four bearing trees:									
	A pine 20 ins. diam., bears N26°E, 192 lks. (126.72') dist., mkd "T21N R29W S4 BT". A tamarack 16 ins. diam., bears S15°35'E, 49 lks.(32.34') dist., mkd "T21N R29W S9 BT". A pine 14 ins. diam, bears S28°20'W 51 lks. (53.46') dist., mkd " T21N R29W S 8 BT". A pine 20 ins. diam. bears N15 [°] 40'W, 115 lks. (75.90') dist., mkd " T21N R29W S 5 BT".									
	<u>1982 H. Gene Warren:</u> I found an iron pin with and aluminum cap set by Booth, 2968S Per Certified Land Corner Recordation vol. 2 page 236									
П.	No sign of 1889 post or BT's Found iron pin 6 ins. below top of asphalt road. (Church St.) Found 1" dia. rebar with yellow cap marked Warren bears East at 16.5 ft. dist. (COS # 348)									
III.	Measured north to the east 1/4 corner of section 5, measured west to the south 1/4 corner of section 5. Both my measurements, GLO distance and previous other surveys correspond. I accepted the found iron pin as a corner of local report being accepted and used by other past surveys									
	Established tv	vo RM's:								
	Set a 60 d nail in 13" Power pole with BT sign N 60°W @ 70.5 ft. dist. Set a 60 d nail in 10" wood fence post with BT sign S 9° E @ 71.1 ft. dist.									
	Magnetic Dec	elination: 17°	East						CERTIFICATION	ROI'ALD A. PEARSON 9008LS CISTER SUR
	0						I. Edda		rmation shown herein is tru	e and correct.
13" Dia	. Power Pole Not	Church Church	EAST 16.5 	ft. Rebar × +	- × ×		direction	in compliance with the	correctly represents work p "Garner Recordation Act" gnature of Surveyor & Seal	Defformed by me or under my (70-22-101, et seq., M.C.A.)
		SKETCH	6 10" Woo					9008LS	SERVICE	
	of Clerk and F on <u>3-6-0</u> XN0.	Recorder, Co		inders	dex plat	and is	assigned	ord" was filed	TDearty	- corner this sheet