1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

Corner <u>1/4 or</u> RECORD	f Secs. 34 & 35 T. 23N R. 30 West P.M.M. Sanders County
GLO 1893	Set a post, 3 ft. long, 3" x 3" square post, 24" in the ground, marked with "1/4" on the W. face. From which:
GLO 1906	<ul> <li>A 10" Fir, bears S 62° E, 37 links dist., marked: "1/4 S35 BT."</li> <li>A 6" Pine, bears N 73°15' W, 4 links dist., marked: "1/4 S34 BT."</li> <li>Resurvey. Found old 1/4 corner in bad state of preservation; re-establish it at the same point as follows.</li> <li>Set a granite stone, 18"x12"x8", 12" in the ground for the 1/4 corner, marked "1/4" on the W. face.</li> <li>From which:</li> <li>A 12" Pine, bears S 70° E, 94 links dist., marked: 1/4 S35 BT.</li> </ul>
1980, 2734S	A 12" Pine, bears S 77 1/2° W, 155 links dist., marked: 1/4 S34 BT. Found no evidence of the original corner. Established the corner by ties into W.W.P. monument. Set 2" pipe, with 2 ½" brass cap in ground. Raise a collar of stone. From which new BT's: A 7" Pine, bears N 24° W, 36.1 ft. A 13" Pine, bears S 69° W, 32.2 ft.
1983, 2734S 1983, 2734S 1989, BLM	<ul> <li>Volume 1, Page 999. Doc. # 155781.</li> <li>COS 656. Found brass cap.</li> <li>COS 657. Found brass cap.</li> <li>Mark Dixon, Cadastral Surveyor. Found original granite stone, 18"x12"x8", firmly set, 12" in the ground, mkd. 1/4 on the W. face.</li> </ul>
	<ul> <li>From which the remains of a 1906 BT:</li> <li>A rotted pine stump, 17" diam., bears S 77 ½° W, 155 links dist., with BT visible on a weathered face.</li> <li>From which bearing trees marked by person(s) unknown:</li> <li>A 23" Pine, bears S 49 ½° W, 58 links dist., with healed blaze.</li> <li>A 15" Pine, bears N 31 ½° W, 36 ½ links dist., with healed blaze.</li> <li>Set a stainless steel post, 30" long, 2 ½" diameter, 20" in the ground, with brass cap.</li> <li>From which the new BT's:</li> <li>A 10" Fir, bears N 39° E, 109 ½ links dist., marked: 1/4 S35 BT.</li> <li>A 9" Pine, bears N 21 1/4° W, 97 ½ links dist., marked: 1/4 S34 BT.</li> </ul>
1990, 2734S	COS 999. Found monument.
<u>FOUND</u> 2001	<ul> <li>Found 3 1/4" diameter BLM brass cap on stainless steel pipe, firmly set, projecting 8" above ground in a collar of stones.</li> <li>From which the remains of record BT's: <ul> <li>A 16" Fir, bears N 39° E, 72.6 ft., with illegible scribing visible on PHB.</li> </ul> </li> <li>Mark a new bearing tree: <ul> <li>A 20" Pine, bears N 28° W, 24.1 ft., marked: RM1.</li> </ul> </li> <li>Paint and place BT tags on bearing trees, and set a MDT survey post with decal 1 ft. N. of corner.</li> <li>See Certificate of Survey on file at the Sanders County Courthouse.</li> </ul>
	20"PINE (RM I) 20"PINE (RM I) 20"FINE (RM I) 20"FIN

PAT INGRAHAM CLERK AND RECORDER D BY: OPpel ¢ sign TO: PROFESSIONAL CONSULTANTS, INC. P.O. BOX 1750, MISSOULA, MT

AND MM

BLM B.C.

3%

SEC.35

SKETCH OF CORNER

CORNER REC PAGE: 32 Pages: 0

SEC.34

RECORDED: 03/02/2004 9:24 KOI: COR RECORD

254623 BOOK: 5

FEE: \$0.00

STATE OF MONTANA SANDERS COUNTY

Corner og., M.C.A.)

tants, Inc Sec.35

2-101, e

CYQI

Professional Consu

Reg. No. 2

Cross Index No.X-17 T. 23 N. R. 30 W. PMM • - Corner this sheet

Signature

ate: 8/01

Employer:

D

Q:CO-STD/152 reated 4/8/92