ial and/r ription of

sequent record used to evaluate the corner position ence found, note discrepancies in the record, state method

ablishing lost

corners.

Description of monument and accessories set to perpetuate the corner position.

J. Description of monument and accessories set to perpetuate the corner position.
Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
Certification must be signed and scaled by Registered Land Surveyor in State of Montana.
Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

17 18 / Corner <u>Section</u> 20 19

T. 24N R. 31W P.M.M. Sanders

_County

1893 GLO RECORD:

SET A GRANITE STONE 18x12x8 INS., 12 INS. IN THE GROUND, FOR COR. TO SECS. 17, 18, 19 AND 20, MARKED WITH 3 NOTCHES ON S. AND 5 NOTCHES ON E. EDGES, FROM WHICH:

A TAMARACK 10 INS. DIAM. BEARS N.16 3/4°E., 27 LKS DIST. MARKED T.24N., R.31W., S. 17 B.T.

A FIR 12 INS. DIAM. BEARS S.46 1/2°E., 29 LKS DIST. MARKED T.24N., R.31W., S. 20 B.T.

A TAMARACK 10 INS. DIAM. BEARS N.16 1/2°W., 78 LKS DIST. MARKED T.24N., R.31W., S. 18 B.T.

A FIR 10 INS. DIAM. BEARS S.65°W., 74 LKS. DIST. MARKED T.24N., R.31W., S. 19 B.T.

FOUND:

NO EVIDENCE FOUND OF CORNER OR ACCESSORIES. THIS AREA HAS BEEN DISTURBED BY LOGGING AND ROAD CONSTRUCTION.


CORNER REESTABLISHED BY DOUBLE PROPORTIONMENT METHOD, SET A 5/8"x24" IRON PIN WITH 2 1/2" ALUMINIUM CAP MARKED:



ON

THOMAS P

SEE CERTIFICATE OF SURVEY NO. 1244



. This "corner Office of Clerk and Recorder, County of Sanders day of 1993 record" was filed for record on the line 925 in was noted on the cross-index plat and is assigned page No. Ungralam Talricia - at 10:32 am 10 life County Official book No. -T. 24N R. 31W N-5PMM Cross Index No. -

corner this sheet