61- 325745

INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner_19, 20, 29 & 30

T. <u>25 N.</u> R. <u>20 W.</u> P.M.M. Lake

_County

Record 1972 - Corner Recordation form by Harry P. Medland on file in Lake County. Sketch on back of corner form indicates a railroad spike was set at the corner location from which: A $\frac{1}{2}$ " pipe bears S 0°20' E, 52.04 feet.

A power pole bears North, 30.35 feet. A gate post bears N 65° W, 42.67 feet.

Found 1988 - by Montana Department of Highways Construction Survey Crew, a railroad spike set flush in southbound lane of U.S. 93 from which a $\frac{1}{2}$ " pipe bears S 0°20' E., 52.04 feet. To perpetuate the corner position during construction 4-5/8" x 30" rebar with 1½" red plastic caps marked "M.D.O.H. R.P." were set as per diagram below.

Set 1990 - After construction at the position of the found railroad spike, set a $3\frac{1}{4}$ " x 30" aluminum monument, 30" in the ground, marked as per diagram below, with metal witness post along side. Corner position is 2 feet north of pavement.

Note: THE VALIDITY OF THIS CORNER POSITION WAS PERPETUATED.	NOT VERIFIED, BUT WAS
Power Pole NI°37'E BZ'	
SB2°07'W 152' Set 3'4"x30" AC. Fower Pole Non Pole No	•= Set 5/8"× 30" Rebar w/11/4 Red Plastic Cap. Marked M.D.O.H. R.P.
SEIPES'W 132' K X BUD KAN	
STATE OF MON NUMENT OO TH NUMENT OO TH NUMEN	CERTIFICATION I. James Lauckner certify the Information shown herein is true and correct. Journey House Signature Ground Party Chieffing I. Robert S. Custer Information certify that this Corner Record correctly the presents work performed in the second correctly the second correctly the presents work performed in the second correctly the second correctly the presents work performed in the second correctly the second correctly
19 20 30 29 55 BB BSC 3325556 5 TR. 1990 MENT OF HIGHNESSET 3'4 X30" Aluminum Cap. SKETCH OF CORNER	by me or under my direction in formplance with the "Coherer Recordation Act, (7.22.01, et accs M.CA. ROBERT/S. Signature of Supreyords Seal 3325S Date: 7/12/90 Reg. No. 3325S SISTERED OF SUPERIOR OF
Office of Clerk and Recorder, County of <u>Lake</u> record" was filed for record on <u>August 20' at la</u> was noted on the cross-index plat and is assigned <u>mickofile</u>	$\begin{array}{c} \text{Sec. 29} \\ \hline 2! 27 \rho \\ \hline 325745 \text{ in} \\ \hline -+29 \\ \hline29 $
RSC:2:dak:217dd/1 -(784 Adopted July 1 1981 Montana Board of Durk	

ly 1, 1981, Montana Board of Professional Engineers & Land Surveyors