Original association subsequent recent match to practicate are contrat position.
Description of evidence found, note discrepancies in the record.
Description of monument and accessories set to perpetuite the corner position.
Stetch of corner, show all pertinent data.
Certification must be signed and acaded by Land Surveyor licensed in the State of Montana.
Fill in index information and above the corner's approximate location within the section diagram.

CERTIFIED CORNER RECORDATION

Corner: <u>S1/4 Corner Section 34 T. 25N R. 21W</u> P.M.M. <u>Lake County</u>

ORIGINAL RECORD: Set 15"x12"x8" lime stone.

EVIDENCE FOUND: No evidence of original stone or accessories found. I find a 3/4" rebar (no cap) 1.4' below road surface. **DISCUSSION:**

Original stone likely destroyed by road construction. Ties to the found 3/4" rebar appear on hwy maps and corner recordation filed as document no.199841

PERPETUATION: See sketch below.



Adopted November 4, 2004, Montana Board of Professional Engineers & Professional Land Surveyors 7_-15