INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners. 3
 - Description of monument and accessories set to perpetuate the corner position.
- Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of 4. accessories, etc
- Certification must be signed and sealed by Land Surveyor registered in the State of Montana. 5.
- Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner SOUTHEAST CORNER SECTION 24

T. 33 N., R. <u>15 E.</u> P.M.M.

HILL County

RECORD GLO 1896

Set a granite stone 16x10x5 ins. 11 ins. in the ground for cor. of secs. 19, 24, 25 and 30 marked with 4 notches on N. and 2 notches on S. edges; dig pits 24x18x12 ins. In each sec. 5 1/2 ft. dist. And raise a mound of earth 4 ft. base, 2 ft. high W. of cor.

FOUND MDT 2004

No evidence of the original corner found.

<u>SET MDT 2004</u>

The position for this corner falls in the centerline of State Secondary Route 232, and was established from right-of-way plans for MDT Project FAP S 301. The transit field notes dated 1934 for these right-of-way plans, indicates the position for this corner was determined from the intersection of existing fence lines. At this position set a 5/8" x 24" rebar with 2" MDT aluminum cap 1" below asphalt surface. Cap is stamped as shown below. Set 4 reference monuments (5/8" x 24" rebar with 2" MDT aluminum cap) as described below:

R.M.: Stamped "T33N R15E, S24, RM, 2004, 11702LS", with an arrow pointing to Section corner bears N41°21'15"W, 53.02' from the Section corner.

R.M.: Stamped "T33N R16E, S19, RM, 2004, 11702LS", with an arrow pointing to Section corner bears N36°06'00"E, 49.84' from the Section corner.

R.M.: Stamped "T33N R16E, S30, RM, 2004, 11702LS", with an arrow pointing to Section corner bears S42°21'48"E, 54.27' from the Section corner.

R.M.: Stamped "T33N R15E, S25, RM, 2004, 11702LS", with an arrow pointing to Section corner bears S46°40'36"W, 58.64' from the Section corner.

Set a witness post with MDT decal 44'+/- Southwesterly at fence corner.



Refer to Certificate of Survey number 554615

R15E R16E	
RM • Unimproved dirt road • RM • N.T.S.	I,, certify the information shown herein is true and correct.
C/L State Secondary 232 and section line	Signature of Ground Party Chief I, <u>Theodore M. Brown</u> certify that this Corner Record correctly represents werk
-X RM • X WITNESS POST • RM S25 SKETCH OF CORNER \$30	berting that us content to the performed by me or under my direction in contrained with the "Center Recordation Act" (0-22-101, et sed., MCA) Signature of Stivetor & Seal 2LS Date: Employer:Montana Department of Transportation
020	Sec. 24
n the cross-index plat, 554617 Fee: \$.00 Bk Pg HILL COUNTY Filed 09/14/2004 At 19:00 AM /	This "corner record" was noted Utams Official
DIANE E. MELLEM, CIK & Rodr By <u>C. (J. U.)</u> Return to: MT. DEPT. OF TRANSPORTATION P HELENA MT 59620-1001	0. BOX 201001 Official
Cross Index No. <u>R25</u> T. <u>33 N.</u> R. <u>15</u>	• — Corner this sheet •