CORNER RECORD (Survey of Record Index) See Instructions

PT3 15+16

T <u>9S</u> R <u>14E</u> P.M.M. SEC <u>25</u> COUNTY Park **MONTANA**

Please check () on Name <u>Park County</u>	e Subdivision <u> </u>	Certificate of S - in Block 7 o	Survey [] If Townsite of Co	ther
and/or Number Block/Lot/Parcel No(s	Book	Page		

Replaced monument at alley corner in Block 7 SE corner Lot 32 - also being SE corner of Lot A, SD 384, which was destroyed in water line construction

.

Exhibit below is a portion of SD 384. Found "A" — 1/2 in. pipe 7 ins. down. Found "B" — yellow plastic capped rebar 6 ins. down under new fill.

Set "C" at record distance from "B" on southerly projection of line "A"—"B". Set a 1 1/2 in. Surv Kap 2 ins. down. Found mangled rebar 10 ins. down in general location. Surv Kap is 4 ft. south of building comer and 4.5 ft. west of water box.



Adopted November 4, 2004, Montana Board of Professional Engineers & Professional Land Surveyors