

STATE OF MONTANA  
DEPARTMENT OF NATURAL RESOURCES AND CONSERVATION  
1424 9TH AVENUE P.O.BOX 201601 HELENA, MONTANA 59620-1601

# GENERAL ABSTRACT

**Water Right Number:** 41L 928-00 STATEMENT OF CLAIM  
**Version:** 1 -- ORIGINAL RIGHT  
**Version Status:** ACTIVE

**Owners:** GLACIER COLONY INC  
PO BOX 2209  
CUT BANK, MT 59427

**Priority Date:** DECEMBER 31, 1950  
**Enforceable Priority Date:** DECEMBER 31, 1950

**Type of Historical Right:** USE

**Purpose (use):** IRRIGATION  
**Irrigation Type:** SPRINKLER

**Maximum Flow Rate:** 1.33 CFS  
THE FLOW RATE OF THIS CLAIM HAS BEEN REDUCED TO 17 GPM PER ACRE.  
THE FLOW RATE MAY BE CONTESTED BY PROPER OBJECTION.

**Maximum Volume:** THE TOTAL VOLUME OF THIS WATER RIGHT SHALL NOT EXCEED THE AMOUNT  
PUT TO HISTORICAL AND BENEFICIAL USE.

**Climatic Area:** 5 - LOW

**Maximum Acres:** 35.00

**Source Name:** HAY LAKE  
**Source Type:** SURFACE WATER

SOURCE LOCATED WITHIN AN INTERIOR DRAINAGE.

**Point of Diversion and Means of Diversion:**

<u>ID</u>	<u>Govt Lot</u>	<u>Qtr Sec</u>	<u>Sec</u>	<u>Twp</u>	<u>Rge</u>	<u>County</u>
1		SWSWSW	2	35N	5W	GLACIER

**Period of Diversion:** MAY 15 TO AUGUST 20

**Diversion Means:** PUMP

**Period of Use:** MAY 15 to AUGUST 20

**Place of Use:**

<u>ID</u>	<u>Acres</u>	<u>Govt Lot</u>	<u>Qtr Sec</u>	<u>Sec</u>	<u>Twp</u>	<u>Rge</u>	<u>County</u>
1	10.00		SWNW	2	35N	5W	GLACIER
2	25.00		NWSW	2	35N	5W	GLACIER
<b>Total:</b>	35.00						

THE PLACE OF USE TOTALS 35.00 ACRES IRRIGATED UNDER A ROTATION  
SYSTEM. THE MAXIMUM NUMBER OF ACRES IRRIGATED IN ANY YEAR IS 5.00  
ACRES.

**Geocodes/Valid:** 38-4743-02-2-02-01-0000 - Y

**Remarks:**

STARTING IN 2008, PERIOD OF DIVERSION WAS ADDED TO MOST CLAIM ABSTRACTS, INCLUDING THIS ONE.

FLOW RATE MAY REQUIRE MODIFICATION BASED ON RESOLUTION OF MAXIMUM ACRES ISSUE.

THE GLACIER COUNTY WATER RESOURCES SURVEY ( 1969 ) APPEARS TO INDICATE 0.00 ACRES IRRIGATED.

USDA AERIAL PHOTOGRAPH NO(S). 182-93 , DATED 09/06/1982 , APPEARS TO INDICATE 0.00 ACRES IRRIGATED.

THE CLAIMED PRIORITY DATE MAY BE QUESTIONABLE. IT APPEARS THE PRIORITY DATE SHOULD BE THE DATE THE SPRINKLER SYSTEM WAS FIRST PUT TO USE.