

Original notes state; Set a wood post , 4 ft. long, 3 ins. square 12 ins. in the ground, raised mound of earth and dug pits.

Found the remining of an old wood post, no definite marks found.

Reestablished the corner position from record calls as shown on the sketch below.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 9-12-79

DIAGRAM OF CORNER:

At the corner point set a 1" x 18" iron pipe with a 2 " brass cap buried 18" deep. Placed a 14"x12"x10" stone alongside the corner along with the old wood post. Mkd. the cap as shown.



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



		Studining of country.
Surveyor's Seal	I, <u>William D. Bayer</u>	
HONTAN BAYER 9 3321 S	certify that the information shown herein is true and correct.	N. RI4W
	William D. Bayer	F
	Signature of Ground Party Chief	21 22 T 28 27 N
	William D. Bayer I,	28 27 N
	certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.	1
TO SURVEY OF	William D. Bayan Signature of Surveyor	• = Corner recorded on the sheet
	3321S Registration Number	
Office of Clerk and Recorder, County	or transite	
This "corner record" was filed for re	cord on the 12th day of Sept. 19.7.9, w	as noted on the cross-index plat and is
		1 A A AL
assigned page No, in book No		
Cross Index No. R-13 T_7N R-14W Mer.		