CERTIFIED CORNER RECORDATION 1/4 Sec. Cor. T. 24 N. R. 31 W . P.M.M. SANDERS County Corner of Secs. S33 S34 Record: T. 1893 original record by Rodney W. and Arthur Page: 40.00 chs. Set a sandstone 30x14x3 ins., 23 ins. in the ground for 1/4 Sec. Cor, marked 1/4 on W., face, from which: A balsam 24 ins. diam., bears S55 1/2°W, 87 lks. dist., mkd. 1/4 S BT. A balsam 6 ins. diam., bears N60 1/2°W, 131 Iks. dist., mkd. 1/4 S BT. <u>1979 Certified Corner Recordation by H. G. Warren:</u> No original record known. No evidence of original corners or accessories found. Set a 1/2 in. x 18 in. rebar with yellow cap 2734S Warren in roadway for East 1/4 corner Section 33. Corner set by proportion from GLO notes. Aspen 4 ins. dia. bears S78°30'E, 29.2 ft. marked RM. Found a 1/2 in. diam. rebar, 8 ins. below grade at the West edge of the county road. II. From which: A birch 16 ins. diam., bears S78°E, 29.2 ft. marked with a healed face. Established 1 new bearing accessory. III. A power pole, bears N16°W, 69.6 ft. Painted and signed the bearing tree. Date of Fieldwork: 11/14/2001 Survey crew: Steve Boyer, Tom Hommel Magnetic declination: 20° East assumed Equipment used: Hand compass and loggers tape U.S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT 59923 (406) 293-6211 CERTIFICATION gan Steven A. Boyer 9756 AND ANZ certify the Informatio ROAD RÖGER O. Green Roger О. COUNTY BEEN, this Corner Rec tlv of Su 29 2 DRIVEWAY 137 Date: 11/14/2001 Reg. No. Employer: U. S. Forest Service NOT TO SCALE SKETCH OF CORNER 245520 Sanders This "corner Office of Clerk and Recorder, County of _ 5 P.M. Sec. 33 3:4 record" was filed for record on February 20, 2002 (a) was noted on the cross-index plat and is assigned page No. 929 rat Ingraham b Mall book No. County Official Depr P.M., MT T. 24N. R. 31W. X-13 Cross Index No.___ · corner this sheet Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors