CG#36 INSTRUCTIONS 1. Original and/or subsequent record used to evaluate the corner position. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated 3. Description of monument and accessories set to perpetuate the corner position. 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc. 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana. 6. Fill in Cross Index & Section Diagram at bottom of sheet. CERTIFIED CORNER RECORDATION Corner \_\_\_\_\_Southwest Section 8 T. 30N R. 30E \_\_\_P.M.M. \_\_\_\_Phillips County Set a granite stone 12x8x7 inches, 8 inches in the ground for 1. Corner to Sections 7, 8, 17 and 18 marked with 4 notches on South and 5 notches on East edges; dug pits 18x18x12 inches in each section 5-1/2 feet distance and raised a mound of earth 2 feet high, 4-1/2 foot base around post.

- 2. Corner was apparently destroyed during road construction. Reset corner from 1934 Montana Highway road plans. This fit a re-recordation of 1987 Department of Highways project RS 242-1(6)0.
- 3. Set 2" aluminum cap marked Department of Transportation. Corner is 5.2' North centerline of highway. Corner is 20.9' S5°22'E of 2.5"x30" aluminum monument marked R.P. → 20.9. Set aluminum post marked survey point 25.5' South. See Amended Certificate of Survey on file.



<ul> <li>Alum Man</li> <li>Result Scap</li> <li>KETCH OF CORNER</li> </ul>	I certify the information shown herein's true and correct. RICHARD H. Signature Original Part Child I Certify that this Corter Record correctly epfermits work performed by me or under my difference or an and the "Corner Recordation Act (112) Corter Accord or and the "Corner Recordation Act (112) Corter Act (112) Signature of Surveyor & Seal Date: 9/93 Reg. No. 9018S Employer: Interstate Engineering,
Office of Clerk and Recorder, County of record'' was filed for record on	. This "corner Sec. 8
was noted on the cross-index plat and is assigned page No	, in
County Offici Cross Index No. <u>J-5</u> T. Adopted July 1, 1981, Montana Board of Professional Engi	30N p 30E