INSTRUCTION 1. Original and/or successful and/or successful and/or successful and/or successful and accessful and accessful and accessful and accessful and	er position. rd, state method of establishing lost or obliterated he corner position. be shown in a sketch example, corner marking,
- CERTIFIED CORNER RECORDATION	
Corner <u>SE cor. Sec 32 - SWCor Sec. 33</u> T. <u>37 N</u> R.	27W P.M.M. Lincoln County
Record:	
Set a sandstone 16x16x10 inches	llischer a the around
marked SC with four notches on	E LO
notches on west face.	East face and three
Dug pits.	
Found original al	
Found original stone with notches rocks - get will a	set in mound of
rocks - Set metal fence post alon	gside stone
See C. of S. No. 541 for adjacent	Corners
	CERTIFICATION
	CERTIFICATION I certify the information shown herein is true and correct.
5/8" rebar	
0 ^{3/8} rebar 27.390 18. 18. 0 18. 18. 18. 19. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10	I. D.K. Marquardt certify that this Corner Record correctly represents work performed
Stone 26.75	by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)
Stone	Signature of Surveyor & Seal
	Date: 7-6-81 Reg. No. 2089 ES
SKETCH OF CORNER	Sec. 32
Office of Clerk and Recorder, County of <u>American</u>	This ''corner
record" was filed for record on the	day of 198/,
was noted on the cross-index plat and is assigned page No.	
book No/ Elisnar L. He Count	y Official Deputy
Cross Index No2- *	