## **PLSS Corner Collection System Data Sheet**

Meridian: MT20 Tier: **<u>T9S</u>** Range: **<u>R10W</u>** Section(s): <u>26/27/34/35</u> County: <u>Beaverhead</u>

## GCDB Point ID: MT20009050100W0 500200

Employee Name: Dan Boers Date: 8/12/2010 Time: <u>11:00am</u>

Found: <u>16"x12"x10" stone lying loose in a 2' diameter collar of stone in a dilapidated NW-SE fence line. On edge</u> facing up found one chiseled notch, on edge facing down found 2 chiseled notches. Reset stone upright in place with 1 notch south and 2 notches east.



Latitude: 45°00'52.3193" N

Longitude: 112°48'12.7523" W

Datum: NAD83(2007)

Approximate orthometric elevation: 6234 ft.

This corner was located as part of a PLSS enhancement project. The location of this corner was not used as control for any legal surveys during this exercise. Horizontal accuracy 1 meter or less.