

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

The original survey was performed in 1873, and there have been no resurveys. The monuments were mostly a friable native sandstone, and the area shows considerable evidence of cultural activity. No original monuments or subsequent reestablishment of monuments were found in this section.


Numerous long-established straight fences and portions of county roads suggest locations of the original corners that are more in harmony with long-established land-use patterns than any other possible interpretation. The exterior corners of Section 28 were therefore reestablished from such physical evidence, as shown in their respective corner records.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: Jan. 1977

Set a Surv Kap at the intersection of a straight fence to the south and the remnants of a straight fence to the east.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



SEE C/S 184

Surveyor's Seal

DIAGRAM OF CORNER:

I, _____, certify that the information shown herein is true and correct.

T1N
R10E
MPM

Signature of Ground Party Chief

Henry A. Rate

I, _____, certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Henry A. Rate
Signature of Surveyor

S28	S27
S33	S34

= Corner recorded on the sheet

3716S
Registration Number

145110

Office of Clerk and Recorder, County of Park

This "corner record" was filed for record on the 25th day of May, 1977, was noted on the cross-index plat and is assigned page No. 10, in book No. one

County Official by Henry A. Rate

fw. 504