

CERTIFIED LAND CORNER RECORDATION

221103

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

NO RECORD AVAILABLE.

NO EVIDENCE FOUND.


DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 12/30/74

At the corner position I set a brass cap in a 2 1/2" concrete filled pipe 30" long. Set 25" in ground, marked:



A mound of stone surrounds the pipe



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. 2366

Surveyor's Seal



I, Dennis C. Muth, certify that the information shown herein is true and correct.

Signature of Dennis C. Muth

Signature of Ground Party Chief


I, Gordon E. Sorenson, certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Gordon E. Sorenson

Signature of Surveyor

2345ES Registration Number

DIAGRAM OF CORNER:



T.16N. R.20W.

● = Corner recorded on the sheet

Clerk and Recorder, County of Lake, State of Montana

This "corner record" was filed for record on the 17th day of March 1975, at 12:20 o'clock P. M., was noted on the cross-index plat and is signed by No. 221103, in book No. C-556

Ethel M. Harding, Clerk & Recorder, County Official By: , Dep.

Cross Index No. G-25 T. 16N R. 20W Mer.