

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

At the 1/4 Corner for Sections 5 & 6, T.19N., R.19W. I find:  
1 set stone, 11" in the ground, marked 1/4 on W. face, no  
T's. Record: A wash boulder, 16"x12"x4", 11" in the  
round, marked 1/4 on W. face, from which a 7" pine  
ears N.89°E., 26 lks. dist. marked 1/4 S5 BT.  
2 7" pine bears S.54°30'W., 83 lks. dist. marked  
1/4 S6 BT.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED  
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


12-70

Date of work:.....

Painted the 1/4 corner stone, yellow.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.  
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

1 3/4" galv. pipe for Sec. Cor. of 5, 6, 7 & 8,  
can be located S.0°9'E., 2650.62 ft.  
dist. from the above corner.  
Note: No evidence of recent survey  
marks were found in area of the  
above corner.



Surveyor's Seal


I, Christopher Babst, Jr.  
certify that the information shown herein is true and  
correct.

Christopher Babst, Jr.  
Signature of Ground Party Chief

I, Christopher Babst, Jr.  
certify that I have carefully performed or reviewed the  
work done on the diagrammed corner as reported on this  
recordation form and approve the same.

Christopher Babst, Jr.  
Signature of Surveyor

DIAGRAM OF CORNER:



◆ = Corner recorded on the sheet

33225  
Registration Number

Office of Clerk and Recorder, County of Lake

As "corner record" was filed for record on the 1 day of March 1971, was noted on the cross-index plat and

Signed page No. C-136, in book No. 197423 3:10 PM  
Wilhelmina Laughlin  
County Official