

CERTIFIED LAND CORNER RECORDATION


DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

U.S.C.S. Witness, iron pipe w/bronze cap.
Centerlines of existing roads.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Set $\frac{5}{8}$ " \emptyset x 24" rebar w/cap @ Cor. location. Date of work: 5/1/78
 Accessories: Nail & Disc in power pole 78.06' N20°W.
 Nail & Disc in power pole 39.11' S45°E.
 U.S.C.S. Witness pipe w/bronze cap, 41.76' S45°W.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



Surveyor's Seal


I,,
certify that the information shown herein is true and correct.

Signature of Ground Party Chief

I, Robert E. Findorff
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Robert E. Findorff
Signature of Surveyor Robert E. Findorff

3976 ES
Registration Number



● = Corner recorded on the sheet

Office of Clerk and Recorder, County of

This "corner record" was filed for record on the day of 19....., was noted on the cross-index plat and is assigned page No....., in book No.....

County Official