

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner East 1/4 Corner Section 25 T. 31N R. 34W P.M.M. Lincoln County


Record: Not known.

Found: BLM brass cap with 3 B.Ts.

A 6" Birch stump bears S 85°30' E 11.2 ft. scribed 1/4 S 30 B.T. Posted by Art 1967.

A 24" Fir bears N 86° E 3.5 ft. posted by Art 1967.

A 10" Hemlock bears S 27°30' W 6.6' scribed 1/4 S 36 B.T. and posted by Art 1967.



SKETCH OF CORNER

CERTIFICATION

I, Jeff Paullin
 certify the information shown herein is true and correct.
Jeff Paullin
 Signature Ground Party Chief

I, Jack H. Ninneman
 certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)
Jack H. Ninneman
 Signature of Surveyor & Seal

Date: 7/10/81 Reg. No. 4661S
 Employer: Ninneman Engineering Inc.

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the 14th of July day of 1981 was noted on the cross-index plat and is assigned page No. 1087 in book No. 1

Clarence L. Vaughn, Jr. Deputy
 County Official

(T-1, T3 & R33) T-25 Sec. 25 31N 34W

Sec.	

corner this sheet