	278	88
--	-----	----

INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

CR FILE

corners.

Description of monument and accessories set to perpetuate the corner position.
Sketch of corner, show all pertinent data which can best be shown in sketch example, corner marking,

 Certification must be signed and sealed by Land Surveyor registered in the State of Montana. Fill in Cross Index & Section Diagram at bottom of sheet 6.

CERTIFIED CORNER RECORDATION

Corner: NW Section 21 T. 1 N. R. 58 E. P.M.M. Carter County Record: 1889 GLO: Scheetz: "Set a sandstone 21x10x4 ins. 16 ins. in the ground for cor. to sec. 16,17,20,21. Marked 3 notches on S. and 4 notches on E. edges. From which: A pine 12ins. diam. bears N82°W, 22lks. Mkd. "T1N R58E S17 BT" A pine 14ins. diam. bears N70°E, 47lks. Mkd "T1N R58E S16 BT

A pine 26ins. diam. bears N88°E, 66lks. Mkd. "T1N R58E S16 BT" All other trees near - all dead. Raise a mound of stone alongside.

1933 GLO: Bandy: Found "Sandstone 16X14X4 ins. above ground, marked as described in the official record; the original bearing trees killed by fire; but still standing. On W. side of cor. stone, Set an iron post, 3ft. long 2ins. diam., 28ins. in the ground, with brass cap marked

T1N R58E		
S 17 S 16		
S 20 S21		
1933		

Dig pits 18x18x12 ins. in each Sec.

Found: 2 1/2in. GL.O. brass cap on 2in. pipe, 6in. above ground, marked as shown above.

Perpetuation:

Place a U.S.F.S 54-9 sign in fence NE 1.0ft, of corner

A 10in. pine bears N81°W, 24.8ft., scribed "T1N R58E S17 BT". Signed with U.S.F.S. 54-3 and 54-9 signs.

