

CERTIFIED CORNER RECORDATION

Corner SEC. COR. 11, 12, 13, 14 T. 4 N R. 11 W P.M.M. DEER LODGE County

ORIGINAL RECORD - GLO 1891

Set a quartzite rock 29x15x4 in. 22 inches in the ground for corner to sections 11, 12, 13 and 14 marked with 4 notches on the south and one on the east edges. Dug pits.

EVIDENCE FOUND: Original stone firmly set in place.

PERPETUATION: Left stone in place.

Refer to C.O.S. #99-A.

	CERTIFICATION A. JAMES NELSON certify the information shown harein is true and correct. Signature Ground Party Chief JENN R. GLENN R. HOWARIS Certify that this Corner Record correctly represents work performed by me or under my direction is compliance with the "Conter Recordation Act" (70-22-101, et res. M.CA Signature of Surveyer a Set SURV Date: 7-21-94 Reg. No. 8376 Summinum
SKETCH OF CORNER	Employer: D J & A ENGINEERS Sec. 12
was noted on the cross-index plat and is assigned page no.	<u>-</u> . This "corner <u>y</u> <u>3.36</u> , in <u></u>
Cross Index No. <u>J - 21</u>	r. <u>4 N r. 11 W PMM</u> • - corner this sheet