INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

Description of monument and accessories set to perpetuate the corner position.
Description of monument and accessories set to perpetuate the corner position.
Sketch of corner, show all perlinent data which can best be shown in a sketch example, corner marking, toppgraphy ties, position of accessories, etc.
Certification must be signed and scaled by Land Surveyor registered in the State of Montana.
Fill in Gross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner \_\_SEC. COR. 1, 2, 11, 12 \_\_\_\_ T. \_ 4 N \_\_\_R. 11 W \_\_\_\_ P.M.M. DEER LODGE \_\_\_\_\_ County

ORIGINAL RECORD - GLO September 1891

Sections 1, 2, 11 and 12 which is a granite stone 12" x 4", 8" above ground marked with 5 notches on south and one notch on east edge.

EVIDENCE FOUND: None

**PERPETUATION:** 

Set 5/8" rebar with 2" aluminum cap (marked as per sketch) from railroad right-of-way plat ties. From which a power pole bears S81°W, 73.5'; a power pole bears S22°E, 49.9'. Placed survey land monument sign on each power pole and set a steel fence post near corner monument.

Refer to C.O.S. #99-A.

			CERTIFY	CATION
381°W 381°W 1994 1994 1994 1994 1994 1994	2 5) Roter o	certify i. <u>Gl</u> certify by me iRecord	atton Act" (70-22-101, et an	CLENN R. GLENN R. GLENN R. Complete Contraction of Complete States work performed an complete State work performed an complete States work performed an an a
POLE	m e.	WER Date:	7-21-94 Ileg. No	
SKETCH OF		OLE Emplo	yer: DUAAL	
Office of Clerk and Recorder, Cou	nty of Door to	dep Thi	s "corner	Sec. 12
record'' was filed for record on		+1994		
was noted on the cross-index plat		No. <u>335</u>	, in	+-++
book No	M. 00.	Fucles on-	Deputy	
	Cross Index No	<u>21 т. 4 N</u>	<u>r. 11 W pmm</u>	- corner this sheet