## CERTIFIED LAND CORNER RECORDATION

## DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Southwest Corner of Srctign 26, Township 4 South, Range 51 East of the Montana Principal Meridian found and Identified. Also the West Quarter Corner of said Section found and identified and a line established between them. Then we Measured on the line North 0010' East 1306.8 feet from the Southwest Corner of said Section 26 and Placed a Monument in the exact location.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER: Date of work: Feb. 23, 1983 The two corners stated above were U.S. Government Brass Cap. Shown below The reestablished Corner Monument is a  $\frac{1}{2}$ " Rebar with an Aluminum cap marked 2357-S and 1/8, shown below 26 1/8 Corner -SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.) General Land Office Map shows 49.60 Chain or 2613.6 feet Bearing N 0010' West 1306.8 feet established West, Southwest 1306.8 feet Southwest Corner East Quarter Corner 1/8 corner Section 26 Section 26 Section 26 DIAGRAM OF CORNER: I, Joe S. Dent Surveyor's Seal certify that the information shown herein is true and correct. 0 Signature of Ground Party Chief I HAS 6 in I./ DINT certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same = Corner recorded on the sheet LAND Signature of Surveyor **Registration** Number 2:46 Pm. #106196 Office of Clerk and Recorder, County of ..... \_\_\_\_\_ This "corner record" was filed for record on the \_\_\_\_\_ day of \_\_\_\_\_\_ 19.23, was noted on the cross-index plat and is Sounty/Official assigned page No....., in book No..... Cross Index No. /-19 R. 51E, Mer. Form 124\_41328