## CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL REGORD (IF KNOWN)

Found: No evidence of corner in existing roadway.

Record: Set 1/4 sec. cor. a post in mound of earth with pits charred stake as per inst-ructions.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work November 1974

Set 5/8" Iron pin and plastic cap at point determined from Montana Highway Department Right-of-Way plans to be 1/4 section corner and projected centerline of highway and N-5 middle section line of Section 17.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.) 1/4 Sec.17 N 89°45'W (Record & Used)
2623, 17'(Meas) 2640' (Record)

Surveyor's Seal

certify that the information shown herein is true and correct.

WILSON 2105 S SURV

Signature of Ground Party Chief

I. WM John Wilson certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

ohn Woon Signature of Surveyor

2/05-S Registration Number

DIAGRAM OF CORNER:

N.

T5N, RIOW, M.P.M. = Corner recorded on the sheet

Office of Clerk and Recorder, County of Lea Lock	l ge
online of the site and another, court, comments	
This "corner record" was filed for record on the//day of	July 1978, was noted on the cross-index plat and is
assigned page No. 204, in book No.	Pally Blume, Discuty
· ·	County Official
Form 125 — 45227	Cross Index No. N-7 T. 5N R. 107. Mer.