## INSTRUCTIONS

Original and,
 Description or

corners.

ecord used to evaluate

equer. .ecord used to evaluate the corner position. .nce found, note discrepancies in the record, state method of estat

st or obliterated

corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner QUARTER BETWEEN SECTIONS 13 AND 18 T. 5N R. 12W-13W P.M.M. DEERLODGE County

1 1905 HENRY B. DAVIS AND EDWIN R. McLAIN

SET A GRANITE STONE, 12X10X6 INS., 8 INS. IN THE GROUND, FOR QUARTER CORNER, MARKED 1/4 ON WEST FACE; FROM WHICH

A PINE, 6 INS. DIAM., BEARS N23°E, 72 LKS. DIST., MARKED 1/4S18BT. A PINE, 6 INS. DIAM., BEARS N28°W, 43 LKS. DIST., MARKED 1/4S13BT.

2. 1997 MIKE D. WELDON

FOUND A WELL SET GRANITE STONE, 8X6X5 INS., ABOVE GROUND MARKED 1/4 ON WEST FACE. A MOUND OF STONE ALONG SOUTH SIDE OF CORNER STONE. FROM WHICH

A PINE SNAG, 6 INS. DIAM., 6 FT. HIGH, BEARS N32'W, 24.0 FT. DIST., MARKED "1/4S13BT". A PINE SNAG, 8 INS. DIAM., 5 FT. HIGH, BEARS N25'E, 46.4 FT. DIST., MARKED "1/4S18BT".


3. 1997 MIKE D. WELDON

I MARK 2 NEW BEARING TREES.

A LODGE POLE PINE 12 INS. DIAM., BEARS \$53°E, 30.8 FT. DIST., \$CRIBED"1/4\$18BT". A LODGE POLE PINE 13 INS. DIAM., BEARS \$60°W, 14.5 FT. DIST., \$CRIBED"1/4\$13BT".

BEARING TREE SIGNS WERE AFFIXED TO THE FRONT AND LAND SURVEY MONUMENT SIGNS TO THE BACK OF THE BEARING TREES. REGISTERED LAND SURVEYOR, "RLS 7692-S" WASHERS WERE AFFIXED TO THE SIDE CENTER OF THE BEARING TREES AT THE BASE.

CORNER FALLS JUST EAST OF A NORTH-SOUTH FENCE, AND AREA SOUTHWEST OF CORNER WAS RECENTLY LOGGED.



SKETCH OF CORNER

CERTIFICATION JOHA, K. BUNCE II n herein is true and correct nature Ground Party Chief certify " WELDON Corner Record that this Corner Record correctly represents work performed or under my direction in compliance with the "Corner ation Act" (79-22-101, et seq.M.C.A.) Lo eldo *X*0. Re oture of Surveyor & Seal Date: 4-98 Reg. No.-7692-S Employer: U.S. FOREST SERVICE

Office of Clerk and Recorder, County of <u>DEERLODGE</u> . This "corner	Sec. 18
record" was filed for record on May 14, 1998	-   -
was noted on the cross—index plat and 3 assigned page No. 511	- -+-
book No. 2 Defuty  Courty Official	
County Official)	
Cross Index No. L-1 T. 5N R. 12W PMM	● - CORNER THIS SHEET