INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- S. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

1/4 Corner Sections 22 & 27 T. 5 N. R. 12 W. P.M.M. <u>Deer Lodge County</u>

ORIGINAL RECORD: (G.L.O.) Not recovered.

SUBSEQUENT RECORD: (1953 B.L.M.)

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 21 ins. in the ground, with brass cap mkd. [as shown below] Bury the original cor. stone and set a 2x4 ins. white wooden post alongside the iron post. Raise a small mound of

stone around the iron post.

EVIDENCE FOUND: Found 3¼" Brass Cap, 0.75' above ground, from which:

A wood 2x4, 2.5' above ground bears north, 2.5 feet dist. A $\frac{5}{8}$ " rebar, 3.8' above ground bears southwest, 0.4 feet dist. A 4 way fence corner bears bears north 2.0 feet dist.

PERPETUATION: Left monument as found.

Located approx. 75 feet south of private driveway, behind storage sheds, approx. 25 feet up gradual north facing

slope.

Date of Survey: October, 2009.



NAD 83 coordinates for this corner:

Latitude = $46^{\circ}09'53.94450"N$ Longitude = $113^{\circ}05'19.09745"W$ NOTE: These coordinates are to be used as a search tool only.

