INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner Sections 22, 23, 26 & 27 T. 5 N. R. 12 W. P.M.M. <u>Deer Lodge County</u>

ORIGINAL RECORD: (G.L.O.) Not recovered.

SUBSEQUENT RECORD: (1953 B.L.M.)

Set an iron post, 28 ins. long, 2 ins. diam., 25 ins. in the ground, with brass cap mkd. [as shown below] set a 2x4 ins.

white wooden post alongside the iron post.

EVIDENCE FOUND: Found 3¼" Brass Cap, 0.6' above ground in mound of stone

PERPETUATION: Left monument as found.


Located at 90° angle break in right-of-way fence on westerly side of fence corner post.

Date of Survey: October, 2009.



NAD 83 coordinates for this corner:

Latitude = 46°09'53.95329"N Longitude = 113°04'41.55993"W NOTE: These coordinates are to be used as a search tool only.



CERTIFICATION

Steve Cummings

herein is true and correct

Signature Ground Party Chief


Kurt A. Luebke

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Signature of Surveyor & Seal

10-27-2009 Reg. No. 13237 S

DJ&A P. C. Employer:



• - corner this sheet