INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.

 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- Description of monument and accessories set to perpetuate the corner position.
- 4. 5. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED	CORNER	BECORD	ATION
CERTIFIED	CURILR	RECURD	ALIUN

CORNER	NORTH 1/4 SECTION 17 T 5 N	R	13 W	_ PMM	ANACONDA- DEER LODGE	COUNTY	
RECORD:	BLM DEPENDENT RESURVEY, JULY 11 TO	SEPT 25, 19	67				
	SET AN IRON POST, 30 in LONG, 2 ½ in DIA 1/4 S17 T5N R13W 1967 FROM WHICH: A PINE 6 INS DIAM., BEARS S 22 °E, 78 LK A SPRUCE 7 INS DIAM., BEARS S 72 ¼ °W	SS MKD 1/4 S1	7 BT	, WITH B	RASS CAP MKD.		
FOUND:	3 ¼ IN BRASSCAP, 5 IN ABOVE GRND MARKED AS SHOWN						
	16" FIR BEARS N 72° W, 4.5 LKS (3 FT) WI 7" PINE BEARS S 22°E, 78 LKS (51.5 FT) W						
SET:	NOTHING						
NOTE:	ALL DISTANCES NOTED FOR BEARING T THE TREE TO THE MONUMENT	REES ARE H	ORIZONTAL	DISTANO	CES FROM THE C	ENTER OF ONTAN	
	SKETCH OF CORNER 16" FIR BT N 72' W, 3 FT BT TAG POSTED 3 !/4 IN BRAS STAMPED AS SH		I,	Signal at this Corner Records Signal 10/17/2002	Group, Inc.	represents work n compliance with l, et seq., M.C.A.) Seal 14725LS	
Office o	f Clerk and Recorder, County of DEER	_		This "c	somer	17	
record" was filed for record on the OCTOBER 21 day of 20 02							
was not	o. 2 Cross Index No. $J-7$	Variat	58 VC DE Official R 13	PUTY W PMI	_ in	orner this sheet	