1. Original and/

INSTRUCTIONS
Original and/ sequer cord used to evaluate the corner position.
Description of against found, note discrepancies in the record, state method of estable corners.

corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

# CERTIFIED CORNER RECORDATION

Corner QUARTER BETWEEN SECTIONS 11 AND 14 T. 5N R. 13W P.M.M. DEERLODGE County

#### 1. 1906 HENRY B. DAVIS AND EDWIN R. McLAIN

SET A GRANITE STONE, 12X10X5 INS., 8 INS. IN THE GROUND, FOR QUARTER CORNER, MARKED 1/4 ON NORTH FACE; FROM WHICH

A PINE, 8 INS. DIAM., BEARS \$71°15'E, 45 LKS. DIST., MARKED 1/4\$11BT. A PINE, 5 INS. DIAM., BEARS \$46°15'W, 101 LKS. DIST., MARKED 1/4\$14BT.

#### 2. 1997 MIKE D. WELDON

FOUND A WELL SET GRANITE STONE, 13X8X7 INS., 6 INS. ABOVE GROUND MARKED 1/4 ON NORTH FACE. FROM WHICH

A PINE, 13 INS. DIAM., BEARS S20'W, 66.7 FT. DIST., WITH MOSTLY OVERGROWN FACE. THE NORTHEAST BEARING TREE IS GONE.

### 3. 1997 MIKE D. WELDON


IN PLACE OF ORIGINAL STONE SET AN ALUMINUM POST, 30 INS. LONG, 2 1/2 INS. DIAM., 28 INS. IN THE GROUND WITH A 3 1/2 INS. ALUMINUM CAP MARKED AS SHOWN. AS A MEMORIAL A DEEP ONE MAGNET WAS PLACED BENEATH THE POST, AND PLACED ORIGINAL STONE, UPSIDE DOWN, ALONGSIDE SIDE OF POST.

I MARK A NEW BEARING TREE.

A LODGE POLE PINE 5 INS. DIAM., BEARS N22'W, 14.8 FT. DIST., SCRIBED"1/4S11BT".

BEARING TREE SIGNS WERE AFFIXED TO THE FRONT AND LAND SURVEY MONUMENT SIGNS TO THE BACK OF THE BEARING TREES. REGISTERED LAND SURVEYOR, "RLS 7692-S" WASHERS WERE AFFIXED TO THE SIDE CENTER OF THE BEARING TREES AT THE BASE.

ANGLE IRON POST WITH PROPERTY BOUNDARY AND LAND SURVEY MONUMENT DECALS SET 1 FT. EAST.




T5N R13W S11 S14 RLS 7692-S 1997

## SKETCH OF CORNER

CERTIFICATION JOHN K. BUNCE II guon shown herein is true and correct Signature Ground Party Chief WELDON Fornec Record lify that this Corner Record correctly represents work performed me or under my direction in compliance with the "Corner ordation Act" (79/22-101, et sea.,M.C.A.) hike D. Welder Signature of Surveyor & Seal Dale: 4-98 Reg. No. 7692-S U.S. FOREST SERVICE

Office of Clerk and Recorder, County of <u>DEERLODGE</u>	This "corner
record" was filed for record on May 14, 1998	
	496
book No. 2 Courry	Yaughn, DEPUTY
Couply	Official



CORNER THIS SHEET

Cross Index No. J=19