CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

NO ORIGINAL EVIDENCE FOUND SEARCHED FOR PINE POST, AND MARKED STONE, MOUND OF EARTH

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


Date of work: 6/13/97

SET S/8 REBAR W/ ALUMINUM

-CAP AS SHOWN BELOW, PUT

-MARILS SIGN ON FENCE POSTS

REESTABLISHED USING SINGLE PROPORTION.



Surveyor's Seal



I, HANS BOHRASEA

certify that the information shown herein is true and
correct.

Signature of Ground Party Chief

William D. Dayer
Signature of Surveyor

DIAGRAM OF CORNER:



= Corner recorded on the sheet

332/5 Registration Number

assigned page No....., in book No.....

Blanche Ledurar
County Official

Cross Index No.V= 7 T. 5M R 14 Me

SECTION 3Z

44040