238932

ł

 Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner N. 1/4 Cor Sec. 5. T. 6N. R. 25E. P.M.M. Musselshell. County

I. ? No corner originally set. II.)

III. Set 5/8" X 24" Rebar with 11/2" Alum Cap at single proportioned position. Corner falls on sandstone outcropping. - Raise mound of stone around corner.

| Set. 11/2" Alum Cap. /4 5 rev ROSE 951915. | CERTIFICATION I. <u>A. Bratton</u> certify the information shown herein is true and correct. <u>Signature Ground Party Chernet</u> I. <u>Bratton</u> Signature Ground Party Chernet Certify that this Corner Record correct Provessors work performed by me or under my direction in Annihilance with the "Cornet Recordation Act" (70-22-101, et sec(M.C.C.L.) NEIL A. <u>Signature of Subreyork Sea0519 LS</u> Date: <u>5/19/82</u> Reg. No. <u>5-19 LS</u> |
|--|---|
| SKETCH OF CORNER | Employer: |
| office of Clerk and Recorder, County of Musselshell . This "corner Sec. Sec. | |
| record" was filed for record on June 15, 1994 | 10:37 AM -++- |
| was noted on the cross-index plat and is assigned page No, in, in, JANE E. MANG by Norman Mull opman, in | |
| Cross Index No. <u>A - 7</u> T. <u>6N - R. 25 E. PMM</u> • - Corner this sheet | |
| Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors | |