INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

Bescription of monument and accessories set to perpetuate the corner position.
 Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of

accessories,

5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner Corner No. 3 MS 34	<u>493</u> T. <u>7N.</u> R. <u>8W.</u> P.M.M. <u>Powell</u> County
1891 GLO Record: (MS 3493)	Set a granite stone 20 x 10 x 10 ins., 14 ins. in the ground marked "3-3493"; from which
	 A Pine 4 ins. in diam., bears N67°45'W, 30.0 ft., mrkd "3-3493 BT". A Pine 4 ins. in diam., bears S54°15'W, 13.0 ft., mrkd "3-3493 BT".
Found (3-24-2010):	Found a firmly set 10" x 10" granite stone protruding 0.8 ft. out of the ground. The original stone had partially legible markings on the south face and an "X" on top; from which
	 A 7" Lodgepole Pine, bears S54°W, 12.8 ft., with partially legible scribing. A 8" dead Lodgepole Pine, bears N69°W, 30.4 ft., with overgrown heel blaze.
Perpetuation (3-24-2010):	Due to the found monuments being firmly set and in good condition we left them as found.
	Note: We set a 5 ft. red angle iron post with USFS decals P54-1 and P71-10, S15°E, 0.5 ft. from the monument. We attach USFS signs 54-3 & 54-9, set a 60D spike at our spot of measurement and paint a 6" red band +/- 6 ft. above the ground on all reference monuments. Original stone was painted red.
	NAD83(CORS96): φ 46°23'33.13"N λ 112°34'34.25"W

Note: Coordinates were established by Real-Time Kinematic (RTK) GPS procedures utilizing Trimble R8 GNSS GPS receivers. Survey ties to controlling PLSS corners and local control points were measured from a base station constrained to the NAD83(CORS96) datum processed utilizing the National Geodetic Survey (NGS) Online Positioning User Service (OPUS) with observation data collected in March, 2010.

Original Stone	certify that this Corner Record Corrective of esonts work performed by me or under my direction in compliance with the "Corner REWITTON Act (70-22-101, et seq., M.CA.), JENKINS March 23301 Signature of Surveyor Set 1975 Date: 03/2010 Reg. No. 9330 Still Employer: Montana Northwest Company P.O. Box 8777, Missoula, MT 59807 406-721-4033 Project No. 1617-09
SKETCH OF CORNER	<u>USFS East Deer Lodge 2009/2010</u>

Office of Clei 165524 Fee: \$0.00 Bk Pg er record" was f POWELL COUNTY Filed 9/2/2010 At 2:50 P Diane S. Grey, Clk & Rcdr By in was noted on Return To: book No. ____ County Official

> Cross Index No. A/B-17/18 T. 7N R. 8W PMM Corner No.3 MS 3493

- Corner this sheet