CERTIFIED LAND CORNER RECORDATION

FUND PROPERLY MARKED STONE LYING NEAR FENCE CORNER. FUND EXISTING BEARING TREE STUMP 5 80.5°E-112.2' AND CUIDENCE OF BEARING TREE LOCATIONS OF 3 OTHER TREES.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER: RE-SET STONE FROM BEARING TREE NORTH OF EXISTING FENCE CORNER EVIDENCE: IMMEDIATELY SET 58" REBAR + CAP TIN 89 R26E SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.) N89°58'W NE COR 8 DIAGRAM OF CORNER: Surveyor's Seal certify that the information shown herein is true and Signature of Ground Party Chief MICHAEL C. ZANCANELLA certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this 8797 S RZ6E

This "corner record" was filed for record on the 16 day of May 1989, was noted on the cross-index plat and is

ssigned page No. in book No. Frances L. Dawson Ly Jane G. Many Deputy

County Official

Cross Index No. E-9 T. 7N R. 26 E. F. Mer. M.

8797 S Registration Number

Signature of Surveyor

= Corner recorded on the sheet