190027

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

DRIGINAL- SANDSTONE 15x13x5 INS., 10 INS. IN THE GROUND MARKED 1/4 ON N. FACE.

DUB PITS 18x18x12'INS. E & W OF STONE AND RAISED A MOUND 1/2' HIGH

\$ 31/2 BASE ALONG SIDE. NOT FOUND.

FOUND - Z" IRON PIPE (THE SW CORNER OF SUBURBAN HOMES SUBDIVISION) 30' NORTH OF THE 5/4 CORNER.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


TIES TO PERPETUATE LOCATION OF Z" IRON PIPE

Date of work: Nauserser., 1973....

1. SET BOAT NAIL IN & PAUE O ROAD 30.0' S. OF PIPE.

2. R/W FENCE IS 1.0' N. OF PIPE.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



	SEC. 14		
	T-8N, R-Z	T-8N, R-25E, M.P.M.	
	MUSSELSHELL	L COUNTY, MONTANA	
Surveyor's Seal	I, Dame H. Bick. certify that the information shown herein is true and correct. Signature of Ground Party Chief	DIAGRAM OF CORNER:	
	certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. Signature of Surveyor	= Corner recorded on the sheet	
	2525s Registration Number		

OF MONTANA, IT OF MUSSELSHELL M Office of Clerk and Recorder, County of Musselshell 9:12am This "corner record" was filed for record on the 26 day of March 1975 was noted on the cross-index plat and is S. Daweau County Official assigned page No....., in book No..... ... T. ... S Form 125 - 45227