CERTIFIED CORNER RECORDATION

Corner NW SECTION 17 _____T, 8N R. 26E P.M.M. MUSSELSHELL County

ORIGINAL RECORD: August 1884 - Set a sandstone 16 x 13 x 5 ins. 10 ins. in the ground for cor. to Secs. 7, 8, 17, & 18 marked 4 notches on South and 5 on East edges. Dug pits 18 x 18 x 12 ins. in each sec. 5 1/2 ft. dits. and raised a mound of earth 2 ft. high 4 ft. base alongside.

SUBSEQUENT RECORD: Certified Corner Recordation, David R. Davis, 4378-S, December, 1992 - Set a 5/8" x 30" rebar with a 2" diameter cap, 0.5 ft. below the surface of gravel road at the position of the 3/8" x 18" rebar with reference monuments.

EVIDENCE FOUND: Found the 5/8" rebar with a RPC to the Northeast, and found a bent rebar to the Northwest. The section corner was not found due to new road construction.

PERPETUATION: Reset the rebar to the Northwest with a 5/8" rebar with a 2" aluminum cap marked "Milestone Surveying 10801 LS". Reset the section corner per 1992 corner recordation using the record distance from both reference monuments. Set a 5/8" rebar with a 2" aluminum cap marked "Milestone Surveying 10801 LS"



Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors