				13	1691	1		
				INSTRU cord used to evaluate th	ne corner position.	Į:		
		corners. 3. Description of	f monument and	, note discrepancies in t accessories set to perp	etuate the corner po	osition.		
		topography ties, 5. Certification r	position of acces must be signed a	ertinent data which ca ssories, etc. nd sealed by Land Surv Diagram at bottom of sl	eyor registered in			
			CERTIF	ED CORNE	R RECO	RDATION		
Corn	erNorth Qua	arter Sec	. 24	T. 15N	R. <u>19E</u>	P.M.M.	Fergus	County
						1		
	14	13		2744.9			- 1/4 LOR	
	23	z4				÷	}	
								
						•		
١								
	The origi	inal sands	stone m	arker was	found we	11 set a	nd in good	condition.
Ь	we set a SEE CERTI	IFICATE OF	rebar F SRUVE	With 2" al Y NO:280 F	UMINUM C OR MOR I	ap along NFORMATI	side. ON.	condition.
T.								
Ŋ								
A								
1								
7								
					· · · · ·			
						I,	CERTIFICATIO	N
						certify the inform	nation shown herein is t	
						Richa	Signature Ground Part ard E. Guei	
			,			/ by me of under	my direction in comp (70-22-101 et seque M.C	presents work performed llange with the "Corner A.)
						striel	Signature of Surveyor	Min
						Date:	-84 Reg. No. 8865	X
		SKETCH	OF CORNI			Employer: <u>G</u>	1enzi Surve	24
	Office of Clerk and Recorder, County of						ner Sec.	• • • • • • • • • • • • • • • • • • •
	d'' was filed i					50		+++
		ross-index pla つ	at and is a	ssigned page	No	24	, in	+-+-+
book	No	ý	-	Alebbe	burty Offici	and by than	ken Barrich	+ $+$ $-$
			-	N	-23	15N 191		

	Cross Index No			R PMM
Adopted July 1, 1981,	Montana Board	of Professional	Engineers &	Land Surveyors
Adopted July 1, 1981,		13691		

corner this sheet