87490

## **CERTIFIED CORNER RECORDATION**

Corner W1/4 Se	ecs.	8	T.	17 N	<b>R</b> .	26W	<b>P.M., MT</b>	Mineral	County

## I. <u>No original record.</u>

- II. <u>No evidence found.</u>
- III. The position for the West ¼ sec, cor. for sec. 8 was determined by single porportionate measurement between the closing corner for secs. 6 and 8 and the sec. cor. for secs 7,8,17 and 18. The exact position was then located on the line between the East ¼ sec. cor. for sec. 7 and the sec. cor. for secs. 7,8,17 and 18. At the exact corner position, as determined by survey, set a 2 1/2 in. diam. aluminum pipe, 30 ins. long, 25 ins. in the ground, with a 3 1/4 in. diam. aluminum cap, marked as shown.



Established two new bearing trees:

A larch, 7 ins. diam., bears N.45°E., 50.1 ft. dist., marked "¼S18 BT".

A larch 6 ins. diam., bears S.5°E., 18.5 ft. dist., marked "X BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

SEE C.O.S. NO. \_\_\_\_\_

Magnetic Declination: 17<sup>1</sup>/<sub>2</sub>° East.



	CERTIFICATION
	I, Ronald L. Benton certify the information shown herein is true and correct.
N.45°E., 50.1 ft. 7" larch	I, Ronald A. Pearson certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Ast" (70-22-101, et seq., M.C.A.)
alum. cap	Signature of Surveyor & Seal Date: <u>4/26/99</u>
	Reg. No.: 9008LS
The G' larch	Employer: U.S. FOREST SERVICE
SKETCH OF CORNER	
87490	Sec. 8
Office of Clerk and Recorder, County of <u>Mineral</u> SFP 9 1999 and was noted on the cross-index plat ar	. This "corner record" was filed for
in book No Statey Mandai	By Stlayes
exempt	untý Official / • - corner this sheet
exempt Rotun TO Mineral County Recurds Cross Index No. G-5 T.	17N <sup>R.</sup> 26W <sup>P.M., MT</sup>
Adapted July 1 1091 Mentana Board of	Brofossional Engineers & Land Supervoya

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors