INSTRUCTIONS

1911172

Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated.

Description of monument and accessories set to perpetuate the corner position.
 Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner Sec Cor. 12 & 13

ORIGINAL RECORD

1893:

Set a limestone 24"x6"x5", 18" in the ground marked with 2 notches on north and 4 notches on south edges. From where a pine 34" in diam. bears S $11\frac{1}{2}$ ° W, 88 lks. A pine 24" in diam. bears N28°W, 113 lks.

SUBSEQUENT RECORD

1965: BLM set iron post 30" long, $2\frac{1}{2}$ " diam. 24" in the ground with brass

Found stumps of original bearing trees and made one new BT. An 8" pine bears S11°W, 53 lks mkd T17N, R27W S 13 BT.

EVIDENCE FOUND

Found BLM brass cap on iron post. Bearing tree evident but no measurements taken.

PERPETUATION

No perpetuation made.

8" PINE () ST (AP 518 SKETCH OF CORNER	CERTIFICATION 1. Glenn R. Howard certify the information shown terein is tryle and correct. Signature Ground Park Chip TA Terry L. Druyvestern
Office of Clerk and Recorder, County of Mexical	Sec.12 & 13
record" was filed for record on	8:08 A.M.
was noted on the cross-index plat and is assigned page No.	, in - 5 12 S7
book No Shirley Mancini	By Carrie Lewis

County Official

Cross Index No. <u>J-25</u> T. <u>17N</u> R. <u>R27W</u> PMM

* - corner this sheet