61- 339551

NT

INSTRUCTIONS 1.Original and/or subsequent record used to evaluate the corner position. 2.Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners. 3.Description of monument and accessories set to perpetuate the corner position. 4.Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking. topography ties, position of accessories, etc. 5.Certification must be signed and sealed by Land Surveyor registered in the State of Montana. 6.Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner <u>N 1/4 Sec. 32</u> T. <u>19 N.</u> R. <u>19 W.</u> P.M.M. <u>Lake</u> County

ORIGINAL RECORD: Set a sand stone, 18x12x6 ins., 12 ins. in the ground

FOUND: No evidence found, corner positioning is in county roadway.

SET: On a straight line between the NE and NW section corners of Section 32 and on the prod of north-south fence line, I set a 5/8" rebar and cap stamped CS&KT RLS 9012 from which:

A telephone pole bears 182° at 29.72'

A headgate shaft bears 350° at 26.75'

SEE BACK FOR SECTION CON	TROL GREGORY B. MARENGO SOLO S
A HEADGATE	CERTIFICATION
DX-OX-DX-OX-OX	I,
58" REUAR & CAP	Signature Ground Party Chief
	I, <u>Gregory B. Marengo</u> certify that this corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seg., H.C.A.) May MB. Mango Signature of Surveyor & Seal
OTELEPHONE POLE	bater 4/92 Reg. No. 9012
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Employer: CS&KT
office of Clerk and Recorder, County of <u>Lake</u> . This "corner record" was filed for record on <u>C-1888</u> <u>at 10:19</u> A MUN 23 '92 was noted on the cross-index plat and is assigned 3395.51 , in <u>May Quar Gelea</u> N/C <u>County Official</u>	
/// Cross Index No V-7 T.	<u>19 N.</u> R. <u>19 W.</u> PMM





L.

. . .