2. Desc corners 3. Desc 4. Sket topogra 5. Certi	ription of evidence ., note discrepar	ch can best be shown in a sket ind Surveyor registered in the	ion. ch example, corner murking,	<sup>iled</sup> ( - 404863	
	CERTIFIED	CORNER REG	CORDATION		
Corner: <u>1/4 Section Corne</u>	<u>r 1 &amp; 12</u> T	<u>19N</u> R	20W P.M.M.	Lake County	
ORIGINAL RECORD:				nd marked 1/4 on N. face; dig pits of earth, 3½ ft. base, 1½ ft. high, N.	
SUBSEQUENT RECORD:	T RECORD: See corner recordation #191265, set a 3/4" Iron pipe as an RM to the true position 21.70' South in Gunlock Road also being a ¼" iron pipe, positioned from fences and best found evidence.				
EVIDENCE FOUND:	Found a 3/4" pipe in	Found a 3/4" pipe in North edge of Gunlock Road.			
PERPETUATION:	the pipe, with the pipe A power pole	e buried inside. The e bears N0°E, 16.2'			
x x x x	Power Pole North 16.2'	/4" Pipe NB3"E	······································		
±1/2 Mile	to Hwy 93 37.6'	Gunlock	Road	-	
	T19N R20W $\sqrt[6]{4}$ $\sqrt[7]{4} \frac{S1}{S12}$ OWARD 8376S		certify the information s <u></u>	Record correctly represents OLE Hormed ction in compliance with the OWARD 2-101, et req., M.E.A. 8376 S CONTRACTOR CONTRACTOR ignature of Surveyor CONTRACTOR Reg. No. 8376 S	
SKETCH OF CORNER			Employer: DJ&A,	<u>. P.C.</u>	
Office of Clerk and Recorder record" was filed for record of was noted on the cross index book No.	DEC 1 7 1999	0'. 20 A-M 40486 RUTH E. HODS unty Official By 3	Jest Mui Just Mui 20W_PMM	Sec. 12 corner this sheet	

NC

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors