## DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found a 15x10x4 inches sandstone marked  $\frac{1}{4}$  and lying loose alongside a skid road. Found a stump hole at record bearing and distance from the proportional point.

Record: Set a sandstone 14x10x4 ins. 10 ins. in the ground marked ½ on the north face from which: A pine, 10 ins. diam. brs. N2OE, 54 lks dist. scribed ½ S 16 BT. A pine, 5 ins. diam. brs. S1OE, 44 lks dist. scribed

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

½ S 21 BT.

Monument marked:

Date of work: NOV. 1973

At record bearing and distance from the section 16 bearing tree stump hole placed a 1" pipe with a 2" brass cap marked as shown:

From which: A 16" ponderosa pine bears N76 30E, 31.1 feet scribed 'RM' with a yellow bearing tree sign attached.

A 16" ponderosa pine bears N49W, 36.6 feet scribed 'RM' with a yellow bearing tree sign attached.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

> T 20 N R 19 W <sup>1</sup>/<sub>4</sub> <u>16</u> 1973 RJS 3538 ES

		DIAGRAM OF CORNER:
Surveyor's Seal	I, William D. Bayer	1
	certify that the information shown herein is true and	AV. T2ON R19W PMM
* ROBERT J. *	correct. <i>William D. Bayer</i> Signature of Ground Farty Chief	$\frac{16}{21}$
	I, Robert J. Shelton	
* ROBERT J. SHELTON 3538 ES *EGISTERE SMEER & LAN	certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. Signature of Surveyor	♦= Corner recorded on the sheet
minuter & LAW		
ffice of Clerk and Recorder, Cou	unty of Lake, State of Montana	
	or record on the 3rd day of November 1975, was	
ssigned page No224353	, in book No. C-603 Ethel M. Hardin Coun	ng, Clerk & Recorder ty OfficiaBy . Milan, Dep
	Cross Index NoN 11	20N R 19W PM Mer.